



अधीक्षण अभियंता का कार्यालय
OFFICE OF THE SUPERINTENDING ENGINEER
कार्य स्थापना अनुभाग, WORKS ESTABLISHMENT SECTION
राष्ट्रीय प्रौद्योगिकी संस्थान कर्नाटक, सुरतकल

NATIONAL INSTITUTE OF TECHNOLOGY KARNATAKA, SURATHKAL

पोस्ट श्रीनिवासनगर, मंगलूरु - 575025, कर्नाटक, भारत / Post Srinivasnagar, Mangaluru - 575025, Karnataka, INDIA.
Phone: [0824] - 2473029, 2473028 Email: se@nitk.edu.in Website: <http://www.nitk.ac.in>

No: 157/QN-01/2025-26/DM

Date: 22.04.2025

NOTICE INVITING QUOTATIONS

The National Institute of Technology Karnataka, Surathkal (in short - NITK, Surathkal or Institute) is an autonomous Institute of the Govt. of India [under the Ministry of Education - MoE] imparting technical and science education. The Institute intends to **"Resetting of damaged reception table and side rack of Vikram Sarabhai guest house and cupboard of Deputy Registrar (F&A) office in NITK"**. The details of work is listed in the sheet enclosed. In this connection, sealed quotations are invited by the undersigned subject to the terms and conditions enumerated here under from the manufacturers/ authorized dealers/ agencies so as to reach this office on or before **30-04-2025 at 03:30PM**. The quotations shall be opened possibly on the same day.

Terms and Conditions:

1. The intending bidder shall quote his rates in the 'Quotation Format' enclosed here with either in his letter head or using the same format. He shall sign each page with seal of the firm. Envelop super scripted as Quotation for **"Resetting of damaged reception table and side rack of Vikram Sarabhai guest house and cupboard of Deputy Registrar (F&A) office in NITK"** due on **30-04-2025 at 03:30PM** and addressed to as "The Superintending Engineer, NITK, Surathkal, Post Srinivasnagar, Mangaluru - 575025" be sent so as to reach this office on or before the due date mentioned.
2. The GST registration number and the PAN number of the bidder shall be mentioned in the quotation. Quotation without this information will not be accepted.
3. Quotation may be dropped in the Tender Box kept in the office or may be sent by post/ courier. It is the responsibility of the bidder to make sure that the quotation is delivered in time. The quotations received after the due date will not be entertained.
4. No advance payment will be made. The payment shall be made only after successful completion of work. No interest will be paid for delayed payments if any.
5. The rate quoted should be firm. No claim for enhancement of rate is admissible after opening of the Quotations.
6. Terms and conditions stipulated in this Notice inviting conditions are binding on the bidder.
7. The undersigned reserve the right of rejecting all the quotations without assigning any reasons thereof.


Superintending Engineer
NITK, Surathkal

अधीक्षक अभियंता / Superintending Engineer
कार्य स्थापना अनुभाग / Works Establishment Section
राष्ट्रीय प्रौद्योगिकी संस्थान कर्नाटक, सुरतकल
National Institute of Technology Karnataka, Surathkal
पोस्ट श्रीनिवासनगर, - 575 025 / Post Srinivasnagar - 575 025

Name and Address of the Bidder:

Contact No:

GST registration number:-

PAN number:-

No:

Date:

QUOTATION

To

The Superintending Engineer,
Office of the Superintending Engineer,
N.I.T.K, Surathkal.

Sl. No	Description of the items	Quantity	Rate in Rs. per each (without Tax)	GST	Amount in Rs. (with Tax)
1	Resetting of damaged curved shape reception table by replacing the damaged plywood sheets of all sides, middle supports and top by providing and fixing new 20mm thick plywood sheets of approved quality with 1mm thick lamination in exposed external sides and two coat of enamel painting to internal side. The work includes cost of fixing the available granite at table top with necessary adhesive & fixtures, cost of all skilled labours, all material, transportation, adhesive, SS fixtures etc. Complete as per the direction of Engineer incharge (including cost of dismantling charges of decayed plywood and removing the debris) Table size: 2.55m(L) x 0.60m(B) x 0.90m(H)	01 Job Work			
2	Resetting of damaged side rack by replacing the damaged plywood sheets of all sides, drawers, cupboard shutters and top by providing and fixing new 20mm thick plywood sheets of approved quality with 1mm thick lamination for all exposed external sides, CB doors, drawers and 6mm thick plywood for drawer bottom with two coat of enamel painting to all internal sides. The work includes cost of fixing the available granite at top with necessary adhesive, fittings like handles, lock for drawer and cabinet door shutters, cost of all skilled labours, material, transportation, adhesive etc. Complete as per the direction of Engineer incharge (including cost of dismantling charges of decayed plywood and removing the debris. Rack size: 2.10m(L) x 0.40m(B) x 0.65m(H)	01 Job Work			

3	Resetting of damaged storage cupboard by replacing the existing plywood and lamination with Marine plywood (exterior grade) BWP grade confirming to IS 710 with 16mm thick for internal & external panels, racks, door shutters and back panels. All the external surfaces of the plywood should be laminated with 1mm thick lamination and internal surfaces should be laminated with 0.80mm thick lamination. All the cut edges of the plywood shall be covered and sealed with 1mm thick PVC edge banding of approved quality and make. All joinery fabrication work shall be done with mini-fix fitting, wooden dowels, modular clips, screws, locks, hinges all the fixtures and fittings like hinges with screws for cabinet door shutter and handle with locking arrangements should be of approved quality & make (SS) etc s per the direction of Engineer incharge. Size: 0.92m(L) x 0.53m(B) x 1.73m(H)	01 Job Work			
Total Amount					

Seal & Signature of the Bidder